

# NEWS

NO. 0185

DECEMBER, 2, 2013

Dear Valued 555 Customers:

**SANKEI INDUSTRY CO., LTD.**  
**305 Takano, Ritto, Shiga, 520-3045, JAPAN**  
**E-mail : info@sankei-555.co.jp**

## New Products

Catalogue page	555 NO.	CAR NAME	MODEL	YEAR	POSITION	/CARTON	START (DELIVERY)
20	<b>SE-N371R</b>	INFINITI FX35	S50	02-	OUT R	40pcs	MIDDLE OF MARCH
20	<b>SE-N371L</b>	INFINITI FX35	S50	02-	OUT L	40pcs	MIDDLE OF MARCH
49	<b>SR-N111</b>	PLATINA	H10(P.S.)	02-	R/L	40pcs	MIDDLE OF MARCH
73	<b>SA-3602R</b>	VITS	NCP10	99-	LOW R	8pcs	MIDDLE OF MARCH
73	<b>SA-3602L</b>	VITS	NCP10	99-	LOW L	8pcs	MIDDLE OF MARCH
90	<b>SB-B082</b>	CHARIOT GRANDIS	N96W	98-	LOW R/L	60pcs	END OF MARCH
98	<b>SB-H082</b>	ACURA TL	UA8	09-	LOW R/L	30pcs	MIDDLE OF MARCH
117	<b>SL-T155</b>	ARISTO	JZS147	91-	REAR R/L	100pcs	MIDDLE OF MARCH
117	<b>SL-T155-M</b>	ARISTO	JZS147	91-	REAR R/L with 2 nuts	100pcs	MIDDLE OF MARCH
119	<b>SL-T605</b>	CROWN	GS141	91-95	REAR R/L	100pcs	MIDDLE OF MARCH
119	<b>SL-T605-M</b>	CROWN	GS141	91-95	REAR R/L with 2 nuts	100pcs	MIDDLE OF MARCH

**THE BEST QUALITY PARTS  
 FROM THE MOST ADVANCED MFG. FACILITIES**

*Tie Rod End. Side Rod Assy. Ball Joint. Idler Arm.  
 Pitman Arm. Center Link. Drag Link. Inner Arm Shaft.*



ISO9001

## New Products

Catalogue page	555 NO.	CAR NAME	MODEL	YEAR	POSITION	/CARTON	START (DELIVERY)
119	<b>SL-T615R</b>	CROWN	UZS145	92-95	REAR R	100pcs	MIDDLE OF MARCH
119	<b>SL-T615R-M</b>	CROWN	UZS145	92-95	REAR R with 2 nuts	100pcs	MIDDLE OF MARCH
119	<b>SL-T615L</b>	CROWN	UZS145	92-95	REAR L	100pcs	MIDDLE OF MARCH
119	<b>SL-T615L-M</b>	CROWN	UZS145	92-95	REAR L with 2 nuts	100pcs	MIDDLE OF MARCH
119	<b>SL-T625</b>	CAMRY	ACV35	01-06	REAR R/L	40pcs	MIDDLE OF MARCH
119	<b>SL-T625-M</b>	CAMRY	ACV35	01-06	REAR R/L with 2 nuts	40pcs	MIDDLE OF MARCH
119	<b>SL-T635</b>	MR-S	ZZW30	99-	REAR R/L	40pcs	MIDDLE OF MARCH
119	<b>SL-T635-M</b>	MR-S	ZZW30	99-	REAR R/L with 2 nuts	40pcs	MIDDLE OF MARCH
121	<b>SL-N030-B</b>	MISTRAL CABSTAR	R20 F24W	94-96 07-	FRONT R/L with Bush Kit	100pcs	MIDDLE OF MARCH
124	<b>SL-N370</b>	INFINITI FX35	S50	02-	FRONT R/L	30pcs	MIDDLE OF MARCH
124	<b>SL-N370-M</b>	INFINITI FX35	S50	02-	FRONT R/L with 2 nuts	30pcs	MIDDLE OF MARCH
127	<b>SL-B090R</b>	ECLIPSE	D53A	00-	FRONT R	40pcs	MIDDLE OF MARCH
127	<b>SL-B090R-M</b>	ECLIPSE	D53A	00-	FRONT R with 2 nuts	40pcs	MIDDLE OF MARCH
127	<b>SL-B090L</b>	ECLIPSE	D53A	00-	FRONT L	40pcs	MIDDLE OF MARCH
127	<b>SL-B090L-M</b>	ECLIPSE	D53A	00-	FRONT L with 2 nuts	40pcs	MIDDLE OF MARCH

Note 1: New items are not listed on the back "555" catalogues (~Vol. 14).

Note 2: START (DELIVERY) indicates available date.

Note 3: Standard spec (without "-B") has already been developed.

Please refer to "Additional Applications", "Information", "Part to be Discontinued" in the Following pages.

## Additional Applications

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	MODEL	YEAR	POSITION
108	<b>SL-2960 *</b> <b>(SL-7755)</b>	54618-6A0A0 ※	OTTI (TURBO) (NISSAN) ※	NA0 ※ NA1 ※	05-06 ※ 06-13 ※	FRONT
108	<b>SL-2960-M *</b> <b>(SL-7755-M)</b>	54618-6A0A0-M ※	OTTI (TURBO) (NISSAN) ※	NA0 ※ NA1 ※	05-06 ※ 06-13 ※	FRONT with 2 nuts
133	<b>SL-6380R</b>	51320-S2R-003 ※	Z ※	PA1 ※	98-02 ※	FRONT R
133	<b>SL-6380R-M</b>	51320-S2R-003-M ※	Z ※	PA1 ※	98-02 ※	FRONT R with 2 nuts
133	<b>SL-6380L</b>	51321-S2R-003 ※	Z ※	PA1 ※	98-02 ※	FRONT L
133	<b>SL-6380L-M</b>	51321-S2R-003-M ※	Z ※	PA1 ※	98-02 ※	FRONT L with 2 nuts


Note 1: The parts with ※ are additions.

Note 2: Additional information is not listed on the back "555" catalogues (~Vol. 14).

Information**OLD**

A number of containing per carton will be changed as follows

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION	/CARTON
128	<b>SL-1685</b>	B26R-28-170 ①	FAMILIA	BJFP	00-	REAR R/L	<b>40pcs</b>
128	<b>SL-1685-M</b>	B26R-28-170-M ①	FAMILIA	BJFP	00-	REAR R/L with 2 nuts	<b>40pcs</b>

**NEW**

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION	/CARTON
128	<b>SL-1685</b>	B26R-28-170 ①	FAMILIA	BJFP	00-	REAR R/L	<b>100pcs</b>
128	<b>SL-1685-M</b>	B26R-28-170-M ①	FAMILIA	BJFP	00-	REAR R/L with 2 nuts	<b>100pcs</b>

Part to be Discontinued

555 No.
SE-3071R
SE-3071L

※They are not available With this information.