

It's recommended to change Idler/Arm and Pitman/Arm at the same time, as both of them are worn away together by heavy friction motions.









Technical Information


(555)

Evaluation testing machine

The temperature and humidity are controlled by the program

 Temperature
 −40°C~+120°C

 Humidity
 0%RH~100%RH



Direction for storage



