

# NEW NEWS

NO. 214

JULY, 3, 2015

Dear Valued 555 Customers:

**SANKEI INDUSTRY CO., LTD.**  
**305 Takano, Ritto, Shiga, 520-3045, JAPAN**  
**E-mail : info@sankei-555.co.jp**

## New Products

Catalogue page	555 NO.	CAR NAME	MODEL	YEAR	POSITION	/CARTON	START (DELIVERY)
49	<b>SR-T830</b>	CAMRY HYBRID	AVV50	11-	R/L	50pcs	END OF NOVEMBER
63	<b>SR-H350</b>	PRELUDE	BB1	92-	R/L	80pcs	END OF OCTOBER

Note 1: New items are not listed on the back "555" catalogues (~Vol. 16).

Note 2: START (DELIVERY) indicates available date.

Please refer to "Additional Applications", "Product Information", "Part to be Discontinued" in the Following pages.

**THE BEST QUALITY PARTS  
 FROM THE MOST ADVANCED MFG. FACILITIES**

*Tie Rod End. Side Rod Assy. Ball Joint. Idler Arm.  
 Pitman Arm. Center Link. Drag Link. Inner Arm Shaft.*



ISO9001


## Additional Applications

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
6	<b>SE-2931</b>		ISIS ※	AM15 ※	04- ※	OUT R/L
37	<b>SE-3281R</b>	45046-97204 ※	DUET (TOYOTA) ※	M100A, M101A, M110A, M111A ※	98- ※	OUT R
37	<b>SE-3281L</b>	45047-97204 ※	DUET (TOYOTA) ※	M100A, M101A, M110A, M111A ※	98- ※	OUT L
48	<b>SR-T520</b>	45510-76010LR ※ For GEAR ASSY 45510-76010 ※	LEXUS CT200H	ZWA10 (LHD) ※	10- ※	R/L
52	<b>SR-N111</b>	49001-00QAALR ※ For GEAR ASSY 49001-00QAA ※	PLATINA	H10 ※	02- ※	R/L
60	<b>SR-6240</b>	53521-S7A-003 ※	STREAM ※	RN1 ※	00- ※	R/L
92	<b>SB-N362</b>	S47P-34-550B ※	BONGO 2WD	SK22T ※	02- ※	LOW R/L
104	<b>SB-6191</b>	51450-SJK-003-1 ※ 51460-SJK-003-1 ※ For ARM ASSY 51450-SJK-003 ※ 51460-SJK-003 ※	ELYSION ※	RRI ※	04- ※	UP R/L
113	<b>SB-S012</b>	45201M60M00-1 ※ 45202M60M00-1 ※ For ARM ASY 45201M60M00 ※ 45202M60M00 ※	ERTIGA ※	AVI414 ※	12- ※	LOW R/L
130	<b>SL-T490</b>		ISIS ※	AM1#, ZM10 ※	04- ※	FRONT R/L
130	<b>SL-T490-M</b>		ISIS ※	AM1#, ZM10 ※	04- ※	FRONT R/L with 2 nuts

“※” marks the additions, not shown in the back issues of “555” catalog (~Vol. 16)

## Product Information

◆ Appearance and figure will be changed as following pictures.



Sleeve(Tube) is joined to Socket tightly with screws and punches.

555 No.	The new shipment starts from
SC-7540	END OF JULY

## Part to be Discontinued

<b>555 No.</b>
SK-2131

※They are not available with this information.