

# NEWS

NO. 296  
FEBRUARY 26, 2020

Dear Valued 555 Customers:

**SANKEI INDUSTRY CO., LTD.**  
305 Takano, Ritto, Shiga, 520-3045, JAPAN  
E-mail : [info@sankei-555.co.jp](mailto:info@sankei-555.co.jp)

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	MODEL	YEAR	POSITION	Qty /CARTON	Available date
16	<b>SE-T801R</b>	45460-09210 ©	SIENNA	ASL30	10-	OUT R	30pcs	END OF JUNE
16	<b>SE-T801L</b>	45470-09130 ©	SIENNA	ASL30	10-	OUT L	30pcs	END OF JUNE
30	<b>SE-B261</b>	4422A110 ©	TRITON	KJ3T	15-	OUT R/L	50pcs	END OF JUNE
39	<b>SE-H761</b>	53540-TAA-023 © -013	STEPWGN	RP1	15-	OUT R/L	60pcs	END OF JUNE
39	<b>SE-H811R</b>	53540-TZ5-A01 ©	PILOT	YF5	16-	OUT R	40pcs	END OF JUNE
39	<b>SE-H811L</b>	53560-TZ5-A01 ©	PILOT	YF5	16-	OUT L	40pcs	END OF JUNE
80	<b>SR-H620</b>	53521-SCV-A01 ©	ELEMENT	YH2	03-	R/L	30pcs	END OF JUNE
84	<b>SR-6780</b>	34160-KG010 ©	STELLA	RN1	06-	R/L	30pcs	END OF JUNE
121	<b>SA-B252R</b>	4013A065 © 54504-6A0A1	MINICAB VAN NV100 CLIPPER (NISSAN)	U61V U71	99- 12-	LOW R	8pcs	MIDDLE OF JULY
121	<b>SA-B252L</b>	4013A064 © 54505-6A0A1	MINICAB VAN NV100 CLIPPER (NISSAN)	U61V U71	99- 12-	LOW L	8pcs	MIDDLE OF JULY

**THE BEST QUALITY PARTS  
FROM THE MOST ADVANCED MFG. FACILITIES**

*Tie Rod End. Side Rod Assy. Ball Joint. Idler Arm.  
Pitman Arm. Center Link. Drag Link. Inner Arm Shaft.*



ISO9001

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	MODEL	YEAR	POSITION	Qty /CARTON	Available date
121	<b>SA-B272R</b>	4013A640 ① 4013A496 54504-6A00E 54504-6A00G	eK WAGON eK CUSTOM eK SPACE eK SPACE CUSTOM DAYZ (NISSAN) DAYZ HIGHWAY STAR (NISSAN) DAYZ ROOX (NISSAN) DAYZ ROOX HIGHWAY STAR (NISSAN)	B11W B11W B11A B11A B21W B21W B21A B21A	13- 13- 14- 14- 13- 13- 14- 14-	LOW R	6pcs	MIDDLE OF SEPTEMBER
121	<b>SA-B272L</b>	4013A639 ① 4013A495 54505-6A00G 54505-6A00J	eK WAGON eK CUSTOM eK SPACE eK SPACE CUSTOM DAYZ (NISSAN) DAYZ HIGHWAY STAR (NISSAN) DAYZ ROOX (NISSAN) DAYZ ROOX HIGHWAY STAR (NISSAN)	B11W B11W B11A B11A B21W B21W B21A B21A	13- 13- 14- 14- 13- 13- 14- 14-	LOW L	6pcs	MIDDLE OF SEPTEMBER
133	<b>SA-H642R</b>	51350-TTA-010 ①	N-BOX	JF3	17-	LOW R	10pcs	END OF AUGUST
133	<b>SA-H642L</b>	51360-TTA-010 ①	N-BOX	JF3	17-	LOW L	10pcs	END OF AUGUST
133	<b>SB-H642</b>	51350-TTA-010-1 ① 51360-TTA-010-1 For ARM ASSY 51350-TTA-010 51360-TTA-010	N-BOX	JF3	17-	LOW R/L	80pcs	END OF JUNE
165	<b>SL-4891</b>	54618-VC300 ①	SAFARI	Y61	02-	FRONT R/L	100pcs	END OF JUNE
165	<b>SL-4891-M</b>	54618-VC300-M ①	SAFARI	Y61	02-	FRONT R/L with 1 nut	100pcs	END OF JUNE
165	<b>SL-4891-B</b>	54618-VC300-B ①	SAFARI	Y61	02-	FRONT R/L with Bush Kit	100pcs	END OF JUNE
172	<b>SL-N595R</b>	56261-3JAOC ①	PATHFINDER	R52	13-	REAR R	50pcs	END OF JUNE
172	<b>SL-N595R-M</b>	56261-3JAOC-M ①	PATHFINDER	R52	13-	REAR R with 2 nuts	50pcs	END OF JUNE
172	<b>SL-N595L</b>	56261-3JAOD ①	PATHFINDER	R52	13-	REAR L	50pcs	END OF JUNE
172	<b>SL-N595L-M</b>	56261-3JAOD-M ①	PATHFINDER	R52	13-	REAR L with 2 nuts	50pcs	END OF JUNE
194	<b>SL-6755R</b>	20470-FL000 ①	IMPREZA SPORT	GT6	16-	REAR R	70pcs	END OF JUNE
194	<b>SL-6755R-M</b>	20470-FL000-M ①	IMPREZA SPORT	GT6	16-	REAR R with 2 nuts	70pcs	END OF JUNE
194	<b>SL-6755L</b>	20470-FL010 ①	IMPREZA SPORT	GT6	16-	REAR L	70pcs	END OF JUNE
194	<b>SL-6755L-M</b>	20470-FL010-M ①	IMPREZA SPORT	GT6	16-	REAR L with 2 nuts	70pcs	END OF JUNE

Note: New items are not listed on the back "555" catalogues (~Vol.18).

Please refer to "Additional Applications", "Correction on NEWS.282" and "Correction" on the following pages.

## Additional Applications

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
15	<b>SE-T401</b>	45046-69245 ※	LAND CRUISER PRADO	GDJ150, KDJ150, TRJ15#, GRJ150, LJ150 ※	17- ※	OUT R/L
44	<b>SE-3271</b>	45046-87401 ※	HIJET	S210P ※	99- ※	OUT L
44	<b>SE-3391</b>	45047-97502 ※	HIJET	S210P ※	99- ※	OUT R
59	<b>SR-T400</b>	45530-60040 ※	LAND CRUISER PRADO	GDJ150, KDJ150, TRJ15#, GRJ150, LJ150 ※	17- ※	OUT R/L
80	<b>SR-H550</b>	53010-T5R-003 ※	FIT ※		15- ※	R/L
99	<b>SB-3841</b>	48610-60070-1 ※ 48630-60040-1 ※ For ARM ASSY 48610-60070 48630-60040	LAND CRUISER PRADO	GDJ150, KDJ150, TRJ15#, GRJ150, LJ150 ※	17- ※	LOW R/L
103	<b>SB-T402</b>	48068-60040-1 ※ 48068-60051-1 ※ 48069-60040-1 ※ 48069-60051-1 ※ For ARM ASSY 48068-60040 48068-60051 48069-60040 48069-60051	LAND CRUISER PRADO	GDJ150, KDJ150, TRJ15#, GRJ150, LJ150 ※	17- ※	LOW R/L
113	<b>SB-N332</b>	54500-9KS1D-1 ※ 54501-9KS1D-1 ※ For ARM ASSY 54500-9KS1D ※ 54501-9KS1D ※	VERSA ※	N17X ※	11- ※	LOW R/L
151	<b>SL-3845</b>		LAND CRUISER PRADO	GDJ150, KDJ150, TRJ15#, GRJ150, LJ150 ※	17- ※	REAR R/L
151	<b>SL-3845-M</b>		LAND CRUISER PRADO	GDJ150, KDJ150, TRJ15#, GRJ150, LJ150 ※	17- ※	REAR R/L with 1 nut
152	<b>SL-3890R</b>		LAND CRUISER PRADO	GDJ150, KDJ150, TRJ15#, GRJ150, LJ150 ※	17- ※	FRONT R
152	<b>SL-3890R-M</b>		LAND CRUISER PRADO	GDJ150, KDJ150, TRJ15#, GRJ150, LJ150 ※	17- ※	FRONT R with 2 nuts
152	<b>SL-3890L</b>		LAND CRUISER PRADO	GDJ150, KDJ150, TRJ15#, GRJ150, LJ150 ※	17- ※	FRONT L
152	<b>SL-3890L-M</b>		LAND CRUISER PRADO	GDJ150, KDJ150, TRJ15#, GRJ150, LJ150 ※	17- ※	FRONT L with 2 nuts
168	<b>SL-N150R</b>	54618-6AZOA ※	ELGRAND ※	E52 ※	08- ※	FRONT R
168	<b>SL-N150R-M</b>	54618-6AZOA-M ※	ELGRAND ※	E52 ※	08- ※	FRONT R with 2 nuts
168	<b>SL-N150L</b>	54668-6AZOA ※	ELGRAND ※	E52 ※	08- ※	FRONT L
168	<b>SL-N150L-M</b>	54668-6AZOA-M ※	ELGRAND ※	E52 ※	08- ※	FRONT L with 2 nuts

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
194	<b>SL-6685</b>		XV ※	GP# ※	12- ※	REAR R/L
194	<b>SL-6685-M</b>		XV ※	GP# ※	12- ※	REAR R/L with 2 nuts and 1 bolt
196	<b>SL-S050</b>	1A03-34-150 ※	AZ-OFFROAD ※	JM23W ※	04- ※	FRONT R/L
196	<b>SL-S050-M</b>	1A03-34-150-M ※	AZ-OFFROAD ※	JM23W ※	04- ※	FRONT R/L with 2 nuts
196	<b>SL-7690</b>	42420-85K01 ※	MR WAGON ※	MF33S ※	11- ※	FRONT R/L
196	<b>SL-7690-M</b>	42420-85K01-M ※	MR WAGON ※	MF33S ※	11- ※	FRONT R/L with 2 nuts


※ marks the additions, not shown in the back issues of "555" catalog (~Vol. 18)

Correction on NEWS. 282

We found that NEWS No. 282 includes wrong OEM#. Please kindly correct your record as below. We apologize your inconvenience.

(Wrong)

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION	PRICE
55	<b>SR-A180</b>	SU003-00832 ① 31460-CA000	86 BRZ (SUBARU)	ZN6 ZC6	12- 11-	R/L	<b>1,080</b>



(Correct)


Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION	PRICE
55	<b>SR-A180</b>	SU003-00832 ① 34160-CA000	86 BRZ (SUBARU)	ZN6 ZC6	12- 11-	R/L	<b>1,080</b>

## Correction

We found that our stabilizer link SL-B015R fits both right and left rear of Mitsubishi OUTLANDER (CW5W, 05-, Japanese Domestic Model). However, SL-B015L does not fit left rear. Please kindly correct your record as below.

(WRONG)

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
177	SL-B015R	MN184194 ©	<b>OUTLANDER</b>	<b>CW5W</b>	<b>05-</b>	REAR R
			OUTLANDER USA DELICA	CV4W, CV5W	07- 07-	
			GALANT FORTIS OUTLANDER SPORT OUTLANDER	CY4A GA2W GF7W	07- 12- 12-	REAR R/L
177	SL-B015R-M	MN184194-M ©	<b>OUTLANDER</b>	<b>CW5W</b>	<b>05-</b>	REAR R with 2nuts
			OUTLANDER USA DELICA	CV4W, CV5W	07- 07-	
			GALANT FORTIS OUTLANDER SPORT OUTLANDER	CY4A GA2W GF7W	07- 12- 12-	REAR R/L with 2nuts
177	SL-B015L	4156A014 ©	<b>OUTLANDER</b>	<b>CW5W</b>	<b>05-</b>	REAR L
			OUTLANDER USA DELICA	CV4W, CV5W	07- 07-	
177	SL-B015L-M	4156A014-M ©	<b>OUTLANDER</b>	<b>CW5W</b>	<b>05-</b>	REAR L with 2nuts
			OUTLANDER USA DELICA	CV4W, CV5W	07- 07-	



(CORRECT)

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
177	SL-B015R	MN184194 ©				REAR R
			OUTLANDER USA DELICA	CV4W, CV5W	07- 07-	
			GALANT FORTIS OUTLANDER SPORT OUTLANDER	CY4A GA2W GF7W	07- 12- 12-	REAR R/L
				<b>CW5W</b>	<b>05-</b>	
177	SL-B015R-M	MN184194-M ©				REAR R with 2nuts
			OUTLANDER USA DELICA	CV4W, CV5W	07- 07-	
			GALANT FORTIS OUTLANDER SPORT OUTLANDER	CY4A GA2W GF7W	07- 12- 12-	REAR R/L with 2nuts
				<b>CW5W</b>	<b>05-</b>	
177	SL-B015L	4156A014 ©				REAR L
			OUTLANDER USA DELICA	CV4W, CV5W	07- 07-	
177	SL-B015L-M	4156A014-M ©				REAR L with 2nuts
			OUTLANDER USA DELICA	CV4W, CV5W	07- 07-	